WOOD DESTROYING PESTS AND ORGANISMS INSPECTION REPORT

Pacific Coast Termite Inc. 40487 Encyclopedia Circle Parises San Francisco 94134-2106 A LICENSED OPERATOR IS HIS/HER FIE	PEST CONTROL AN EXPERT IN D. QUESTIONS						
Pacific Coast Termite Inc. A LICENSED OPERATOR IS HIS/HER FIE	PEST CONTROL AN EXPERT IN D. QUESTIONS						
40487 Encyclopedia Circle OPERATOR IS HIS/HER FIE	AN EXPERT IN D. QUESTIONS						
Tel 510-252-0801 Fax 510-252-0826 SHOULD BE HIM/HER.	OPERATOR IS AN EXPERT IN HIS/HER FIELD. QUESTIONS RELATIVE TO THIS REPORT SHOULD BE REFERRED TO						
Ordered by: Property Owner and/or Party of Interest: Report sent to: Fariba Lance Fidelity National Title Fidelity National Title 1130 Brussels St 2099 Gateway PI, ste 500 2099 Gateway PI, ste 50 San Francisco, CA 94134-2106 FSBC-0272201502 FSBC-0272201502 408-859-9098 San Jose, CA 95110-1093 San Jose, CA 95110-1093 408-337-4313 408-337-4313							
COMPLETE REPORT □ SUPPLEMENTAL REPORT □ REINSPECTION	REPORT 🗌						
General Description: 2 Story, Single Family House, Attached Garage, Occupied and Furnished Inspection Tag Posted: Garage Other Tags Posted: None noted							
An inspection has been made of the structure(s) shown on the diagram in accordance with the Structural Pest Control Act. Detached porches, detached steps, detached decks and any other structures not on the diagram were not inspected.							
Subterranean Termites ☑ Drywood Termites □ Fungus/Dryrot ☑ Other Findings ☑ Further Inspe	ction 🗵						
Key: 1 = Subterranean Termites 2 = Drywood Termites 3 = Fungus/Dryrot 4 = Other Findings 5 = Unknown Further	dings 5 = Unknown Further Inspection						

Seller X Minnie Fields Date X 11-22-22 Diagram Not To Scale 1b 3d 3c 1d 3b 3b 3b 1a1c 1d Garage 5b 1d 4a 1b 4b 3b 5a 1b

de

nspected By:	Antonio Castillo	State License No.:	FR55951	Signature:	
--------------	------------------	--------------------	---------	------------	--